

LECTURE NOTES
ON
ENERGY CONVERSION-1(TH-1)
DIPLOMA COURSES
4TH SEMESTER
ELECTRICAL ENGINEERING


PREPARED BY- ER. BISWAJIT MALLIK(SR. LECT. ELECTRICAL)

DEPT. OF ELECTRICAL ENGINEERING

GOVT. POLYTECHNIC BALASORE

① Electro-mechanical energy conversion principles

The basic principle of EMEC device is law of conservation of energy, i.e. energy can neither be created nor be destroyed but it can be changed from one form to another form.



iii) Coupling field may be a elec. field or magnetic field. The energy storing capacity of magnetic field is about 3000 times more than that of in the elec. field.

That's why magnetic field is used as a coupling field in most of the EMFC devices. In electrostatic voltmeter coupling field is electro. Field.

$$\begin{aligned}
 \text{energy density} &= \frac{m \mathbb{F}}{B^2} \\
 &= \frac{1}{2 \mu_0} \\
 &= \frac{1.6^2}{2 \times 1 \times 10^{-7}} \\
 &= 1.01 \times 10^6 \text{ J/m}^3
 \end{aligned}
 \quad
 \begin{aligned}
 \text{EF} &= \frac{1}{2} C_0 E^2 \\
 &= \frac{1}{2} \times 8.85 \times 10^{-12} \\
 &\quad \times (1 \times 10^6)^2 \\
 &= 9.927 \text{ V/m}
 \end{aligned}$$

energy balance eqn

motor

$$\begin{aligned}
 \text{elect. energy i/p} - \text{ohmic energy losses} &= \left[\begin{array}{l} \text{energy loss} \\ \text{in coupling + in the} \\ \text{field due} \\ \text{to } (W_h \& W_e) \end{array} \right] \\
 + \left[\begin{array}{l} \text{energy loss in} \\ \text{mechanical system} \end{array} \right] &+ \left[\begin{array}{l} \text{energy stored} \\ \text{in the rotating} \\ \text{body} \\ \frac{1}{2} I \omega^2 \end{array} \right] + \text{mech. energy O/P}
 \end{aligned}$$

$$W_{\text{elect}} = W_{\text{Field}} + W_{\text{mech.}}$$

under steady state condⁿ

under S.S. condⁿ energy stored in the coupling field & the mechanical systems are constants. so

Power balance eqⁿ (differentiation of energy balance
eqⁿ w.r.t. time under s.s.
condn)

$$P_{in} = V I$$

$$P_{\text{mech}} = E_b I \quad \text{if } n=0, E_b=0, P_{\text{mech}}=0$$

→ For small changes the energy balance

$$\text{eqn becomes } dW_{\text{elec}} = dW_{\text{Fid}} + dW_{\text{mech}}$$

→ The analysis of EMEC device is based on the energy balance eqⁿ is conjunction with

Faraday's laws of electromagnetic induction

→ In Generator, the coupling field system interacts with mechanical system & absorbs mechanical energy from it. Coupling field supplies elec. energy to the elect. system after converting mechanical energy into EE.

→ In motors, coupling field system interacts with elect. system & absorbs elect. energy from it. & the coupling field supplies mech. energy to the mechanical system.

→ coupling term terms are E_b & torque in motor, E_g & torque in generator,


② Working principle of DC Generators

(Rotating armature & stationary field)

DC Generators = S.G + commutators



with slip rings

case - I ($0-180^\circ$)









$$\theta = \omega t$$

$$\theta \propto t$$






case - II ($180-360^\circ$) after $\frac{1}{2}$ cycle





Case-II (after $\frac{1}{2}$ cycle)





①

i) with slip rings brush B₁ is always in contact with conductors AB whether it exists under North pole or south pole.

→ brush B₂ is always in contact with CD whether it exists under N pole or south pole.

ii) if conductor AB is under 'N' pole, the current in it is \textcircled{X} . & brush B₁ polarity becomes -ve after $\frac{1}{2}$ cycle rotation, conductor AB comes under south pole. The induced current in it is \textcircled{O} . & brush B₁ polarity becomes +ve. From the above it is observed that the brush polarity is alternating.

→ Therefore with slip rings the brush voltage induced current & current inside the armature conductors are AC, & $f = \frac{PN}{120}$ Hz

with commutator/ split rings

i) The brush B_1 is always in contact with the conductor that exists under north pole only & brush B_2 always in contact with the conductor that exists under south pole only.

→ in case i) brush B_1 is in contact with conductor, the induced current in it is \times . & the brush B_1 polarity becomes -ve.

→ after $\frac{1}{2}$ cycle rotation conductor CD comes under the North pole, the induced current in it becomes \times . Brush B_1 is in contact with conductor CD through commutator segment ② therefore B_1 brush polarity is -ve; from the above it is observed that the brush polarity is fixed i.e., uni-directional.

→ with split rings, the brush voltage & load current are uni-directional & 50 Hz . But the current inside the armature conductors is AC & its frequency $f = \frac{N}{P} 120 \text{ Hz}$.

Note: The current inside the armature conductors of DC Generator is AC & its f is $\frac{PN}{120}$.

Q) If, DC gen is running at 1500 rpm, what is f of current inside the armature conductors?

- a) 0 Hz b) 50 Hz c) 60 Hz d) 100 Hz

→ commutator in DC generators behaves as a mechanical rotating switch, uncontrollable full wave rectifier.

→ The methods to increase DC o/p voltage & to reduce ripples in the DC o/p voltage


are i) by connecting more no. of armature coils in series in each parallel path

ii) by using flat topped main field flux distribution





The no. of pulses in the DC o/p voltage for every 180° = the no. of armature coils connected in series in each parallel path

i)

$$\theta = 0^\circ$$



$$\theta = 90^\circ$$




avg. value

→ commutator in DC Generator behaves as a mechanical rotating ~~uncontrolled~~ full wave rectifier.

→ The methods to increase DC o/p Voltage & to reduce ripples in the DC o/p Voltage are i) by connecting more no. of armature coils in series in each parallel path


ii) by using flat topped main field flux distribution
The no. of pulses in the DC o/p voltage for every 180° = the no. of armature coils connected in series in each parallel path



Generators

$$T_{pm} \rightarrow \omega_s$$

T_{em} \downarrow braking torque



$$\left. \begin{aligned} T_{pm} &= T_{em} + T_B + T_J \\ T_{pm} &= T_{em} + B \cdot \omega_s + J \cdot \frac{d\omega}{dt} \end{aligned} \right\} \text{frictional losses}$$

at steady state

$$\omega_s = \text{const.}, \quad T_{pm} = T_{em} + B \cdot \omega_s$$

$$\omega_s = \frac{T_{pm} - T_{em}}{B}$$

at N.L

$$I_a = 0, \quad T_{em} = 0$$

$$\omega_s = \frac{T_{pm}}{B} \quad \Rightarrow \quad T_{pm} = B \omega_s = T_B$$

$$T_{pm} \cdot \omega_s = B \omega_s \cdot \omega_s$$

$$P_{in} = \text{losses}$$

$$\text{at loaded cond'n} \quad \omega_s = \frac{T_{pm} - T_{em}}{B}$$

→ motor action ~~and~~ also takes place in generator

Due to generator action, the current carrying conductors, present in the magnetic field therefore, torque is produced. The direction of this torque is acting opposite to the pm torque that's why this electromagnetic torque produced is called braking torque or ~~re~~counter torque.

\propto reaction torque or magnetic drag.

→ The direction of braking torque can be found by applying Fleming's Left hand rule.





~~torque balance~~ ~~action eqn~~


→ Under no-load condⁿ, generator demands mechanical power to overcome its internal losses

→ Under loaded condⁿ, generator demands mechanical energy in order to overcome the opposition due to motor action in the generator.





DC motor working principle


DC motor = synchronous motor + commutator with slip rings





with split rings





→ with slip rings DC supply is connected across brushes with B_1 as +ve & B_2 -ve



Case - 1
with ^{SR} brush B_1 is always in contact with AB conductor & brush B_2 is always in contact with CD conductor whether they exist under N-pole or S-pole. In Fig (1) AB under N-pole the current in it is (\times) , due to supply V & conductor CD under 'S' pole, the current in it is (\ominus) .

→ Now the torque is produced in the ccw direction by using this torque, the motor completes half cycle rotation. In Fig (2) AB under south pole, current in it (\times) & CD under N-pole, current in it is (\ominus) Now the torque is produced in the cw direction. From the above it is observed that the avg. torque over one rotation is zero.

- with split rings, the DC supply is connected as brushes with B_1 +ve & B_2 -ve with commutator, brush B_1 , always in contact with the conductor ~~ex.~~ which exists under N-pole & brush B_2 is always in contact with the conductor ~~which~~ which exists under S-pole,
- in Fig ③ B_1 , is in contact with conductor AB the current in it is (\times) . CD is under south pole, the current in it is \ominus bcoz B_2 brush is in contact with CD conductor, now the torque produced in the ccw direction & the arm, completes half cycle rotation.
- After half cycle rotation, in Fig ④ B_1 brush is in contact with CD conductor current in it is (\times) & B_2 brush is in contact with AB conductor, current in it is (\odot) . Now the torque is produced in the ccw direction. From the above it is observed that the unidirectional torque is produced, i.e. in ccw direction.
- with commutator, the motor the brush voltage is DC but current in the arm. conductors is AC & its $f = \frac{NP}{120}$.
- commutator in DC motor converts DC across the brushes into AC in the armature conductors. Hence it behaves as a mechanical rotating uncontrolled inverter.

Note.. The current in the armature conductors of DC m/c is always AC & its $f' = \frac{PN}{120}$

Generator



→ Generator action will also take place in the motor, due to motor action, armature conductors are rotating in the magnetic field, they cut the magnetic flux & dynamically induced emf is produced. The direction of this induced emf is acting opposite to the supply voltage. That's why this induced emf is called back emf or counter emf or reaction voltage.

→ The direction of back emf can be found by applying ~~Right Hand~~ FRHR.

→ The back emf produced in the armature conductors is AC & its frequency is $f = \frac{NP}{120}$

but across the brushes back emf appears as DC. The armature current is proportional to the potential diff $(V - E_b)$.

$$I_a = \frac{V - E_b}{R_a}$$

$$I_a V = I_a E_b + I_a^2 R_a$$

$$P_{in} = P_{mech} + \text{Arm. co losses}$$

$$P_{\text{mech}} = E_b I_a = T_{\text{em}} \times \omega_\alpha$$

$$T_{\text{em}} = \frac{P_{\text{mech}}}{\omega_\alpha} = \frac{E_b I_a}{\omega_\alpha}$$

→ commutator makes the armature poles

stationary w.r.t stator or space

→ The main field poles are stationary in DC m/c, the relative speed b/w the stator poles

& rotor poles is equal to zero i.e,

Stator poles & rotor poles are stationary w.r.t each other.

→ The rotor poles w.r.t rotor is rotating in opposite direction.

→ The relative speed b/w rotor poles & armature equal to $2n_\alpha$.

→ The DC m/c construction is possible with rotating armature & stationary field system configuration only due to commutator action otherwise the commutator action will be failed.

Construction of DC m/c

(i) stator

(ii) Yoke / Frame

(iii) Field poles

→ Pole core

→ Pole shoe

→ Field wedg

(i) Rotor

(i) Armature core


(ii) commutator

(iii) brushes

(iv) Armature

windings

* Yoke / Frame



Yoke : cast iron (small m/c) DC

cast steel (large DC m/c)

steel = iron + carbon

functions

- i) It acts as a protective cover for entire m/c.
- ii) It provides mechanical support to the Field poles.

Poles :-
iii) It provides return path to the main field flux.

Note : Flux passing through the yoke or frame

is $\frac{\phi}{2}$ where ϕ = FLUX / pole.



iv) Flux passing through the armature core section is equal to $\frac{\phi}{2}$.

Field Poles

pole core : cast steel.

Function :

- i) It carries Field wdg & it provides mechanical support to the Pole shoe.
- ii) It acts as an electromagnet when the Field wdg's are excited.



Funcn: It distributes magnetic flux uniformly

in the air gap. Therefore avg flux/pole

increased.

→ generated voltage & torque produced are also increased.

→ pole arc / pole pitch ratio is $0.7 - 0.9$.

→ main field flux distribution in the DC/m_c is a flat-topped waveform.

Q) Why pole shoe is a laminated part in the DC M/C?

A: to improve commutation, open slots are preferred in the DC M/C.

→ with open slots flux density in the pole faces

varies w.r.t time, emf induced in the pole shoe &

it produces eddy currents which causes eddy current losses to minimise eddy current losses

in the pole shoe, it is made with cast steel laminations.

→ The armature flux completes the path through the pole shoe, when the DC M/C is subjected to variable loads the flux passing through pole shoe varies w.r.t time. Therefore emf induced & it produces eddy currents & eddy current losses, to minimise this pole shoe is a laminated part.



L_c

$R \uparrow$


$$\downarrow L_c = \frac{N^2}{R \uparrow}$$

$U_\delta \downarrow$

less sparking

closed slot

$$U_\delta = \frac{2I_c L_c}{T_c}$$




$R \downarrow$

$$L_c = \frac{N^2}{R \downarrow}$$


$U_\delta \uparrow$

more sparking



→ ~~less slot area → less flux~~


Inter slot area \rightarrow more flux




$$I_{ad} = \text{const.}$$

$$I_a = \text{const.}$$

$$\phi_a = \text{const.}$$



Variable I_{ad}



for m=1



$$\phi_a \rightarrow \text{variable}$$

$$e \neq 0$$

(4) Field winding



Field wdg



$$\uparrow R_{sh} = \propto \frac{l}{a}$$

$\rightarrow R_{sh} \rightarrow$ high ($100 - 250 \Omega$)
(order of 100)

\rightarrow more turns
of thin copper wires.

$$\downarrow R_{se} = \propto \frac{l}{a}$$

$\rightarrow R_{se} \rightarrow$ less ($< 1 \Omega$)

\rightarrow few turns of thick
copper wire.

Rotor side

1) Armature core

\rightarrow silicon steel lamination in order to reduce both hysteresis losses & eddy current losses.

Functions : i) to accommodate armature wdg's

ii) it provides low reluctance path to the main field flux.

2) Commutator

\rightarrow it contains no. of commutator segments

\rightarrow commutator segments are made with hard drawn copper or silvered copper.

\rightarrow No. of commutator segments required

Is no. of armature coils 600

→ commutator segments are insulated from each other by mica insulation of thickness 0.6 to 0.8 mm, its dielectric strength is 30 - 40 Volts.

brushes

→ made with copper, carbon, electrographite, metallic/graphite.

Copper

(i) Carbon → small DC m/c

(ii) electrographite → LV / ~~DC~~ brush

→ metallic graphite → General purpose brush


→ metallic graphite → LV, High I DC m/c

↓ brush drop


0.25 - 0.5 V/brush

Function


→ It collects the current from armature conductors through a commutator segments or brushes send the current into armature conductors through a commutator segments.





→ mica ($0.6 - 0.8 \text{ mm}$)
 $30 - 40 \text{ V}$



yoke





Advantages of carbon brush over copper brush

- (i) self lubricating property due to this brush
- Frictional losses becomes less, efficiency increased.
- (ii) high thermal stability i.e. high melting point due to this current collection capacity of brush increased.
- (iii) it improves the commutation i.e. less sparking at the buses.
- (iv) brush drop is constant bcoz it has negative temp. co-efficient.

disadvantages

more brush drop

Note. (i) commutator m/c have closed armature windings.


(ii) ac m/c have open armature wdg's.

Q) 4P, dc m/c armature have 10 coils, resistance of each coil is 0.1Ω , what is the resistance b/w any two adjacent commutator segments.

$$A: R_{1 \& 2} = \frac{R_c \times (n-1) R_c}{R_c + (n-1) R_c}$$

$$= \frac{0.1 \times 9 \times 0.1}{0.1 + 9 \times 0.1}$$

$$= 0.09\Omega$$



④ Armature windings

conductor

It is the active length of copper wire which takes active part in the energy conversion process, emf induced & torque produced.




Furn

$1 \text{ turn} = 2 \text{ conductors}$

coil


coil contains any no. of turns but it has only 2 coil sides, conductors in each coil side = turns of a coil

conductors in a coil = $2 \times \text{turns/coil}$



single turn coil

$AB, DE \rightarrow$ coil sides



two turn coil



n-turn coil


$BCD \rightarrow$ overhang at end

→ overhang portion can be reduced by using short-pitched coils & by using more no. of poles in the m/c.

→ overhang portion of coil is also called inactive copper in the rotating m/cs. conductors are called active copper in the rotating m/cs.

Types of armature windings based on coil sides/slot

1) single layer wdgs



→ one coil side occupies entire slot area

→ $S = \text{slots}, c = \text{coil}$

$$C = \frac{S}{2}$$

→ small AC m/c

$u=1$

double layer wdgs

each slot → even coil sides

top → odd in 2 layers



bottom

even


no.

→ $S = \text{slot}$

$$C = S$$

④ commutator m/cs
(DC m/c)

large AC m/c



$u = \text{coil sides} / \text{slot}$

$$C = \frac{1}{2} u s$$

$u = 2$ default

Q) how many commutator segments are required in 4P, 36 slots DC m/c. a) 18 b) 36 c) 72 d) 144

Ans: $C = \frac{1}{2} \times 2 \times 36$, $u = 2$

Q) how many commutator segments are required in 4P, 36 slot DC m/c without 4 coil sides/slot.

A: $C = \frac{1}{2} \times 4 \times 36 = 72$, $u = 4$.

Pole pitch

The peripheral distance b/w adjacent identical

points on the adjacent poles is called pole



pitch. pole pitch $\equiv \frac{s}{p} = 180^\circ$

coil span

The distance b/w coil sides of a coil is called coil span.

if coil span = PP \rightarrow full pitched wdg

if $s < PP$ \rightarrow short pitch wdg




(residual voltage)

with short pitched coil, $L_c \downarrow$, $U_x \downarrow$, less sparking

→ emf remains same in DC m/c for short pitched wdg.

→ For AC m/c, emf \downarrow , for short pitched wdg.



→ with short pitched wdg, E_g is same as that of full pitched wdg in DC m/c, due to flat topped flux distribution.

→ ~~short~~ short pitched wdg are used in DC m/c in order to improve the commutation.

Types of armature wdg based on armature

coil end connection

i) lap winding

ii) wave winding

Lap winding

The finishing end of a coil under one pole is connected to the starting end of next coil existing under some pole pair through a commutator segments.

wave winding

The finishing end of one coil exist under one pole pair is connected to the starting end of the next coil exists under its adjacent pole pair.

back pitch

- The distance b/w top & bottom coil sides of a same coil measured on back side of armature is called back pitch.
- back pitch Y_b is always odd.

$$Y_b = \frac{2c}{p} + k$$

where k may be an integer or fraction that makes Y_b odd.

front pitch

The distance b/w coil sides that are connected to the same commutator segment is called front pitch.

- front pitch Y_f is always odd.
- if $Y_b > Y_f \rightarrow$ progressive winding
i.e. Left \rightarrow Right
or clockwise direction
- if $Y_b < Y_f \rightarrow$ retrogressive winding
i.e. Right \rightarrow Left or
CCW direction

Commutator pitch

The distance b/w commutator segments to which starting & finishing ends of the same coil are connected is called commutator pitch

$$\rightarrow Y_c = \pm m, \text{ Lap winding}$$

$$= \frac{c \pm m}{P/2} \rightarrow \text{wave winding}$$

+ → progressive wdg

- → retrogressive wdg

$m=1$, simplex

$m=2$, duplex wdg

$m=3$, Triplex wdg

winding pitch

The distance b/w consecutive coils of similar top or bottom coil sides measured in the direction of wdg progress is called winding pitch.

$$\rightarrow \text{wdg pitch } Y_w = 2Y_c$$

$$= Y_b - Y_F ; \text{ Lap}$$

$$= Y_b + Y_F , \text{ wave}$$

Lap winding

double layer

$$S = 12$$

$$C = S$$


$$P = 4$$

$$Y_b = 8 - 1 = 7$$

$$Y_F = 8 - 3 = 5 \quad S/P = 3 \quad PP = \frac{S}{P} = \frac{12}{4} = 3$$

$$Y_c = 2 - 1 = 1$$


$$Y_w = 3 - 1 = 2 \\ = Y_b - Y_F$$



wave winding

$$S = 12 \quad Y_b = 8 - 1 = 7$$

$$N = 16 \quad Y_f = 13 - 8 = 5$$



$$Y_b > Y_f \quad \text{progressive}$$

$$Y_c = \frac{c \pm 1}{P/2} =$$

$$\therefore Y_w = 2 Y_c = Y_b + Y_f = 7 + 5 = 12 \\ = 13 - 1 = 12$$

Dummy coils

if commutator pitch Y_c is ^{an} integer, dummy coils are not required, otherwise dummy coils are required. In \rightarrow Lap winding, $Y_c = \pm m$ always integer.

\Rightarrow so dummy coils are not required.

\rightarrow In wave wdg, $Y_c = \frac{c \pm m}{P/2}$ may be integer or ^{fraction}

\rightarrow if it is integer, dummy coils are not required, if it is not an integer, dummy coils are required.

\rightarrow dummy coils are used to provide mechanical balance. dummy coils are electrically isolated coils i.e. they are not connected to the commutator.

\rightarrow No. of dummy coils are $\Theta_1 = c' - c$

$$c' = \frac{1}{2} VS$$

$$c = \text{active coils} = Y_c \cdot \frac{P}{2} \mp m$$

Wave

$$S = 12$$

$$P = 4$$

$$c' = 12 = \frac{1}{2} VS$$

$$Y_C = \frac{12 \pm 1}{4/2} = \frac{13}{2} \text{ or } \frac{11}{2}$$

take $Y_C = 6$ $\therefore = 6.5 \text{ or } 5.5$

$$C = 6 \cdot \frac{4}{2} - 1 = 11$$

dummy coil = $C - c$
 commutator segments required = 11
 $= 12 - 11 = 1$ coil

duplex $m = 2$, $Y_C = \frac{12 \pm 2}{4/2} = \cancel{8} \text{ or } 7 \text{ or } 5$

no dummy coil is required

multiplex wdg's

multiplex wdg's are preferred intentionally to increase the no. of parallel paths.

→ Generally simplex wdg's are preferred in DC mic.

Lap

$$Y_C = \pm m \quad \boxed{A = mP}$$

$$\underline{m=1}, \quad Y_C = \pm 1, \quad A = P$$

$$\underline{m=2}, \quad Y_C = \pm 2, \quad A = 2P$$

$$\underline{m=3}, \quad Y_C = \pm 3, \quad A = 3P$$

∴ For a given armature if $A \uparrow$

$V_A, I \uparrow$

wave

$$Y_C = \frac{c \pm m}{P/2}, \quad \boxed{A = 2m}$$

$$\underline{m=1}, \quad Y_C = \frac{c \pm 1}{P/2}, \quad A = 2$$

$$\underline{m=2}, \quad Y_C = \frac{c \pm 2}{P/2}, \quad A = 4$$

$$1) m = 3, Y_C = \frac{C \pm 3}{P/2}, A = 6$$

no. of brushes required = A for respective of wdg

$$\text{lap } S = 8, P = 4, A = 4$$

$$Y_b = \frac{2C}{P} \pm k = \frac{2 \times 8}{4} \pm k = 4 \pm k - k = 4 + 1 = 5$$

$$\text{simplex } Y_C = 1$$

$$Y_w = 2Y_C = Y_b - Y_F$$

$$2 \times 1 = 5 - Y_F$$

$$Y_F = 5 - 2 = 3$$

$$Y_b = 5$$

$$\textcircled{1} + 5 = 6$$

$$3 + 5 = 8$$

$$5 + 5 = 10$$

$$7 + 5 = 12$$

$$9 + 5 = 14$$

$$11 + 5 = 16$$

$$13 + 5 = 18 \textcircled{2}$$

$$15 + 5 = 20 \textcircled{4}$$

$$Y_F = 3$$

$$6 - 3 = 3$$

$$8 - 3 = 5$$

$$10 - 3 = 7$$


$$12 - 3 = 9$$

$$14 - 3 = 11$$

$$16 - 3 = 13$$

$$18 - 3 = 15$$

$$20 - 3 = 17 \textcircled{1}$$



$$P_0 = E I_a = E \cdot 4 I_c$$

if one brush is removed (2 parallel paths removed)

$$P' = E \cdot 2 I_c$$

$$P' = \frac{P}{2}$$

if two adjacent brushes are removed

$$P'' = E \cdot I_c$$

$$P'' = \frac{P}{4}$$

if two opposite brushes are removed

$$I = 0$$

$$E = 0$$

$$P = 0$$

Lap, $P = 6$, ~~E, P~~ $\rightarrow P = E \cdot 6 I_c$


if one brush is removed

$$E' = E, P' = E \cdot 4 I_c$$

$$\frac{P'}{P} = \frac{E \cdot 4 I_c}{E \cdot 6 I_c} = \frac{2}{3} \text{ ~~opp~~}$$

Simplex wave

$$A = 2$$



$$P = E \cdot 2 I_c$$

if one brush is removed


$$P' = 0$$

equaliser rings

- In Lap winding, each parallel path is distributed under one pole pair only. due to flux unbalanced emf's induced in the parallel paths are unequal & the circulating currents comes into picture,
- due to circulating currents, some brushes are overloading, commutation becomes poor (sparking at the brushes).
- to avoid over-loading of brushes & to reduce flux unbalance effect equaliser rings are used in the lap windings.
- In wave winding each parallel path is distributed under all poles. Therefore due to flux unbalance, both the parallel paths effects equally & circulating currents are not present in the m/c. Therefore equaliser rings are not required with wave wdg.
- equaliser rings are made with copper & core placed on the back side of armature. The equipotential points of the armature core are connected to the equaliser rings.
- The distance b/w equi-potential points is

$$Y_{eq} = \frac{2C}{D}$$

if it is integer, then only equalised connections are possible.




$$\rightarrow \text{if resistance of each parallel path} = 0.1\Omega$$

Formature CV loss = $I_a^2 R_a$

$$= 4 I_p^2 R_p = 4 \times 50^2 \times 0.1$$


$$= 1000 \text{ W}$$

AG under $N_1 S_1 \downarrow N_2 S_2 \downarrow$, due to wear of bearing



$$I_C = \frac{V_{B_2 B_4}}{R_{B_2 B_3} + R_{B_3 B_4}} = \frac{4}{0.1 + 0.1} = 20 \text{ Amp}$$

Armature copper losses = $2 \times (70)^2 \times 0.1 + 2 \times (30)^2 \times 0.1$
 $= 1160 \text{ W} \quad \uparrow, \eta \downarrow$



Applications

Lap \rightarrow HV LV, H I

wave \rightarrow HV, L I

large DC m/c \rightarrow composite winding

Advantages of wave winding


- i) only 2 buses brushes are required.
 - ii) equiliser rings are not required.
 - iii) in large commutator m/c, composite windings or Fog leg windings are used. composite winding is a comb' of simplex lap & multiplex wave winding.
- This winding does not require dummy coils & equiliser rings

Circuit model of a DC mic


$Z = \text{total conductors}$

$A = \text{No. of parallel path}$

each conductor \rightarrow cell (σ, e)



Thevenin's equivalent ckt



$$E_{th} = E_{oc} = E$$

$$E = e \times \frac{Z}{A}$$


$$E \propto \frac{1}{A}$$

$$\frac{E_{Lap}}{E_{Wave}} = \frac{A_{Wave}}{A_{Lap}}$$

$$\rightarrow \frac{E_{Lap}}{E_{wave}} = \frac{2}{P}$$

④ $R_{th} = R_a$

path resistance $R_p = \sigma \frac{Z}{A}$



$$R_{\text{sh}} = R_a$$

$$R_a = \frac{R_p}{A} = \frac{\gamma Z}{A}$$

$$R_a = \gamma \cdot \frac{Z}{A^2}$$

$$R_a \propto \frac{1}{A^2}$$

$$\boxed{\frac{R_{aw}}{R_{al}} = \left(\frac{AL}{Aw} \right)^2 = \left(\frac{P}{2} \right)^2}$$

(+) $I_a = A \cdot I_c$

$$\boxed{\frac{I_{al}}{I_{aw}} = \frac{AL}{Aw} = \frac{P}{2}}$$

(*) $\frac{P_{Lap}}{P_{wave}} = \frac{E_L \cdot I_{al}}{E_w \cdot I_{aw}} = \frac{3}{P} \times \frac{P}{2} = 1$

$$\therefore \boxed{P_{Lap} = P_{wave}}$$

(Q) 4 pole, DC m/c have 100 conductors emf induced in each conductor is 2V. The max^m current without overheating of armature supplied by the conductor is 10Amp. Resistance of each conductor is 0.01 Ω. calculate power rating of DC m/c with lap winding & wave winding & calculate armature copper losses with lap winding & wave winding?

A: $Z = 100, E = 2V, I_E = 10A$

$$\gamma = 0.01 \quad P_{lap} = E_L \cdot I_{al}$$

$$= \gamma \times \frac{E_L \times Z}{A} \times I_{al} = 500 \text{ Watt}$$

$$E_L = \epsilon \times \frac{Z}{A}$$

$$I_{al} = A I_c$$

$$P_{lap} = E_L I_{al} = \epsilon \times \frac{Z}{A} \times A I_c$$

$$= 2 \times 100 \times 10$$

$$= 2 \text{ kW}$$

$$P_{wave} = E_\omega \cdot I_{aw} = \epsilon \times \frac{Z}{A} \times I_c$$

$$= 2 \text{ kW}$$

$$R_{al} = \sigma \cdot \frac{Z}{A L^2} = 0.01 \times \frac{100}{\pi^2} = \frac{1}{16} \Omega$$

$$R_{aw} = \sigma \cdot \frac{Z}{A \omega^2} = 0.01 \times \frac{100}{2^2} = \frac{1}{4} \Omega$$

$$\text{Armature copper loss (wave)} = I_{aw}^2 R_{aw}$$

$$= (0.20)^2 \times \frac{1}{4}$$

$$\text{Total copper loss} = \frac{400}{4} = 100 \text{ W}$$

$$\text{Max. (lap)} = (40)^2 \times \frac{1}{16} = 100 \text{ W}$$

Q1-15 $P=49$, $\text{waveform } E=230V$, $P=5 \text{ kW}$, $N=1500 \text{ rpm}$

Both windings disconnected by lap $\therefore E=?$, $P=?$


$\therefore P = \text{Same } E = 5 \text{ kW}$

$E_L = ?$

$$\frac{E_L}{E_W} = \frac{A_w}{A_L} \Rightarrow \frac{E_L}{230} = \frac{25}{4}$$

$$\therefore E_L = 115V$$

⑤ Emf eqn & torque eqn



$$E = \epsilon x \frac{Z}{A}$$

$$\frac{N}{60} \rightarrow \text{rps} \quad \text{one rotation}$$

$$\text{Flux cut} = P \phi_{\text{sub}} = \phi_2$$

$$\text{Time} = \frac{60}{N} \text{ sec} = \epsilon t_2$$

$$e = \frac{d\phi}{dt} = \frac{\phi_2 - \phi_1}{t_2 - t_1} = \frac{P \phi}{60 \text{ rad}} \quad e = \frac{\phi P N}{60} v$$

$$E = \epsilon x \frac{Z}{A}$$

$$* \boxed{E = \frac{P \phi Z N}{60 A}}$$

$$E \propto \phi N$$

$$\boxed{\frac{E_2}{E_1} = \frac{\phi_2}{\phi_1} \times \frac{N_2}{N_1}}$$

$$\rightarrow \text{Lap} \quad A = P, \quad E = \frac{\phi Z N}{60 A}$$

$$\text{if } P = 2P, \quad E = \text{same}$$

$$\rightarrow \text{wave}, \quad A = 2$$

$$E = \frac{P \phi Z N}{60 \times 2} \quad V$$

$$E \propto P$$

$$E = \frac{P \phi Z n}{60 A}$$

$$\omega = \frac{2\pi N}{60} \text{ rad/sec}$$

$$E = \frac{\phi Z P}{A} \times \frac{\omega}{2\pi}$$

$$\frac{H}{60} = \frac{\omega}{2\pi}$$

$\therefore E = k \phi \omega$

$$k = \frac{Z P}{2\pi A} = \text{DC m/c constant}$$

Torque eqn

$$P = T_{em} \times \omega = EI_a$$

$$T_{em} \times \omega = EI_a$$

$$T_{em} = \frac{P}{\omega} = \frac{EI_a}{\omega} \text{ N-m}$$

$$T_{em} \times \frac{2\pi N}{60} = \frac{\phi Z P}{60 A} \times I_a$$

$$T_{em} = \frac{1}{2\pi} \left| \frac{\phi Z I_a P}{A} \right| \text{ N-m}$$

$$T_{em} = k \phi I_a \text{ N-m}$$

$$T_{em} \propto \phi I_a$$

$$\frac{T_2}{T_1} = \frac{\phi_2}{\phi_1} \times \frac{I_{a2}}{I_{a1}}$$

6) Types or DC m/c

separately excited DC m/c

DC m/c

self excited DC m/c

series

compound

shunt

compound \rightarrow long shunt


\rightarrow short shunt

PM DC m/c permanent magnet DC m/c

$\phi = \text{const.}$ $E \propto N$

no field wdg is present


$T \propto I_a$



$$F = V + I_a R_a + B \cdot D$$

$$E = k \phi \omega_s = k_1 \omega_s$$



$$T = k \phi I_a = k_1 I_a \quad k_1 = \frac{\phi Z P}{2\pi A}$$



$$E_b = V - I_a R_a - B \cdot D$$

$$B \cdot D = 2 \times B \cdot P / \text{each brush}$$

Separately excited DC Generator



$$V = I_L R_L$$



$$E_g = V + I_a R_a + B \cdot D$$

$$I_L = I_a$$

$$P_o = V I_L$$

$$P_g = E_g I_a$$

Separately excited motor



$$* E_b = V - I_a R_a - B \cdot D$$

$$I_L = I_a$$

B.D. neglected



$$P_{in} = V I_L$$

$$I_a E_b = I_a V_a - I_a^2 R_a$$

\downarrow

$$P_{\text{mech}} = P_{\text{in}} - \text{armature copper loss}$$

$$P_{\text{mech}} = V I_a - I_a^2 R_a$$

Cond'n for max^m P_{mech} or P_{out}

$$\frac{dP_{\text{mech}}}{dI_a} = 0$$

$$V - 2I_a R_a = 0$$

$$I_a = \frac{V}{2R_a} = \frac{V - E_b}{R_a}$$

$$E_b = \frac{V}{2}$$

$$N \text{ at } \max^m P_{\text{mech}} = \frac{100 N_{\text{N.L}}}{2}$$

⑧ $V = 200 \text{ V}$ E_b at max^m P_{mech} $E_b = 100 \text{ V}$

⑨ $N_0 = 1200 \text{ rpm}$ N at Φ max P_{mech} = ?

$$N \cdot L = I_a \approx 0 \quad E_{b1} = V$$

$$N_0 \propto E_{b1} = V$$

$$\text{At max } P_{\text{mech}}, E_{b2} = V/2$$


$$N_2 \propto E_{b2} = \frac{V}{2}$$

$$\frac{N_2}{N_1} = \frac{E_{b2}}{E_{b1}}$$

$$\Rightarrow \frac{N_2}{N_0} = \frac{V/2}{V} = \frac{1}{2} \Rightarrow N_2 = \frac{N_0}{2} = 600 \text{ rpm}$$

= Speed at $\max^m P_{\text{mech}}$

DC shunt generator



KCL

$$I_a = I_{sh} + I_L$$


$$I_{sh} \propto \frac{V}{R_{sh}}$$

$$\phi \propto I_{sh}$$

KVL

$$E_g = V + I_a R_a + B \cdot D$$

DC shunt motor



KCL

$$I_L = I_{sh} + I_a$$

$$I_a = I_L - I_{sh}$$

$$\phi \propto I_{sh} = \frac{V}{R_{sh}} = \phi_{const.}$$

→ constant flux motor

$$\text{KVL} \quad E_b = V - I_a R_a - B \cdot \phi$$

DC shunt M/C

$$E = V \pm I_a R_a \pm B \cdot D$$

$$I_a = I_L \pm I_{sh}$$

$$I_{sh} = \frac{V}{R_{sh}}$$

+ → gen

- → motor



Q) DC belt driven shunt generator supplies power to the DC busbar. If its belt snaps (PM failed) the M/C behaves as a)

a) DC shunt generator rotating in the same direction
b) DC shunt generator rotating in the opposite direction

b) DC shunt generator rotating in the opposite direction

c) DC shunt motor rotating in the same direction

d) DC shunt motor rotating in the opposite "



$$T_{em} \propto \phi \cdot I_a$$

$$\hookrightarrow ccw$$

$$\omega \rightarrow cw$$

$$T_{em}' \propto \phi' \cdot I_a'$$


$$\propto \phi' (-I_a)$$

$$T_{em}' = -T_{em}$$

$$\hookrightarrow ccw$$

$$\omega \rightarrow ccw$$

DC series generator



$$I_a = I_L$$


$$\phi \propto I_a = I_L$$

$$KVL$$

$$E_g = V + I_a R_a + I_a R_{se} + B.D.$$

$$E_g = V + I_a (R_a + R_{se}) + B.D.$$

DC series motor



$$T_L = F_L$$

$$KVL$$

$$V = E_b + I_a R_a + I_a R_{se} + B.D.$$

$$E_b = V - I_a R_a - I_a R_{se} - B.D.$$

D.C series m/c

$$E = V \pm I_a(R_a + R_{se}) \pm B \cdot D$$

$$I_a = I_L$$

$$\phi \propto I_a = I_L$$


+ → gen

- → motor

Compound m/c

long shunt : shunt field connected across armature & series field

armature & series field




$$\phi_{se} \propto I_a \because \phi_{sh} \propto I_{sh}$$

$$I_{sh} = \frac{V}{R_{sh}}$$

$$\underline{\text{KCL}} \quad I_a = I_L + I_{sh}$$

$$\underline{\text{KVL}} \quad E_g = V + I_a(R_a + R_{se}) + B \cdot D$$

long shunt compound motor



$$\phi_{se} \propto I_a$$

$$\phi_{sh} \propto I_{sh} = \frac{V}{R_{sh}}$$

$$\underline{\text{KCL}} \quad I_L = I_a + I_{sh}$$

$$I_a = I_L - I_{sh}$$

$$\underline{\text{KVL}} \quad V = E_b + I_a R_a + I_a R_{se} + B \cdot D$$

$$E_b = V - I_a R_a - I_a R_{se} - B \cdot D$$

long shunt m/c

$$E_b = V \pm I_a (R_a + R_{se}) \pm B.D$$

~~motor~~ $I_a = I_L \pm I_{sh}$

+ $\rightarrow G$

- $\rightarrow M$

$$\phi_{se} \propto I_a$$


$$\phi_{sh} \propto I_{sh} = \frac{V}{R_{sh}}$$

Trade off

short shunt

Shunt Field is connected across armature only

i) Generator




KVL

$$E_g = V + I_a R_a + I_L R_{se} + B.D$$

$$I_{sh} = \frac{V + I_L R_{se}}{R_{sh}}$$

ii) motor



KCL

$$I_L = I_a + I_{sh}$$

$$I_a = I_L - I_{sh}$$

KVL

$$V = E_b + I_a R_a + I_L R_{se} + B.D$$

$$E_b = V - I_a R_a - I_L R_{se} - B.D$$


$$I_{sh} = \frac{V - I_L R_{se}}{R_{sh}}$$

D C compound mic short shunt

$$E = V \pm I_a R_a \pm I_{L,RSE} \pm B.D$$


$$I_a = I_L \pm I_{sh}$$

$$\varphi_{se} \propto I_a ; \quad \psi_{sh} \propto I_{sh} = \frac{V + I_L R_{se}}{R_{sh}} \quad + \rightarrow \text{Gen} \\ - \rightarrow \text{motor}$$



$$\phi = \phi_{Sh} + \phi_{Sk}$$


Cumulative compound



$$\phi = \phi_{sh} - \phi_{se}$$

differential compound

Under normal working condⁿ / $\phi_{sh} > \phi_{se}$



Q) cumulative compound generator supplies power to the DC bus. if its prime mover is failed then it behaves as a

Q) cumulative compound

as a (c) cumulative compound motor rotating in the same direction

b) C C m rotating in opposite w

C) P C M ~~20~~ 11 11 11 11 11

D₂-DCM " " " Same y

Armature Reaction

①

The effect of armature flux (ϕ_a) on main field flux (ϕ_m) is called Armature reaction.

Effects

1) Demagnetisation (Reduction of net flux)

→ In Generator, Generated voltage & terminal voltage will decrease.

→ In motor, speed is increased & torque is decreased.

2) Cross magnetisation (distortion of air gap flux) → sparking at the brushes

GNA (Geometrically Neutral axis)

→ GNA is the axis which is always perpendicular to the main field flux or d-axis.

→ The GNA is itself quadrature axis and also called Brush axis, since the brushes are always fixed along the GNA.

→ GNA is also called axis of commutation, since commutation process takes place along the brush axis GNA.

MNA (magnetic neutral axis)


→ It is always perpendicular to the resultant flux distribution.

(Leading pole tip) LPT

It is the pole end at which the armature conductors are entering into the magnetic field.



(Falling Pole tip) TPT

Pole end at which the armature conductors are leaving from the magnetic field.





Ⓐ At no-load ($I_f \neq 0, I_a = 0$)

only field current (I_f) is considered, $I_a = 0$





Ⓑ On-load condⁿ ($I_f = 0, I_a \neq 0$)

only armature current is considered:



Ⓒ on-load condⁿ (practical case) ($I_f \neq 0, I_a \neq 0$)

both I_f & I_a are considered



(3)

Under no-load condⁿ, armature current is zero.
Armature flux is zero. MNA coincides with GNA.

Under loaded condⁿ, in Generator at LPT armature flux is acting opposite to the main field flux.

At the trailing pole tip the armature flux adds to the main field flux and at the leading pole tip opposes the main field flux therefore strengthening effect at trailing pole tip & weakening effect at leading pole tip.
Therefore the flux under the pole becomes less than no-load value. This is called demagnetising effect.



The demagnetising effect can be overcome by adding extra turns to the main field winding or by increasing cross-section of field winding copper wire. This method requires more copper, cost of the machine increases, Field copper loss ↑, efficiency of the M/C ↓.

Cross magnetisation

Armature flux crosses the main field flux.
Hence this flux is called cross flux & effect due to this flux is called cross magnetising effect.

Effects of cross magnetisation

- i) MNA shifts from GNA by an angle θ in the direction of Generator rotation or opposite to the motor rotation.
- ii) iron losses will be increased, efficiency will decrease.



(4)

- The component ϕ_d is in direct opposition to the main flux (ϕ_m). It has a demagnetising effect on the main field poles. It is called demagnetising component of armature reaction.
- ϕ_c is right angles to the ϕ_m . It distorts the main field. It is called the cross-magnetising or distorting component of armature reaction.


Conclusion

- i) with brushes located along G.N.A (i.e. $\theta = 0^\circ$), there is no demagnetising component of armature reaction ($\phi_d = 0$). There is only distorting or cross magnetising effect of armature reaction.
- ii) with brushes shifted from G.N.A armature reaction will have both demagnetising & cross magnetising component. Their magnitude depend on amount of shift which is directly proportional to the armature current.



(5)

Demagnetising & cross magnetising conductors



Let z = total no. of armature conductors

I = current in each armature conductor

$$= I_a/2 \dots \text{For wave winding}$$

$$= I_a/p \dots \text{For lap winding}$$

θ_m = Forward lead in mechanical degrees

The no. of armature conductors in angles AOC &

$$\text{BOD is } \frac{4\theta_m}{360} \times z$$

As two conductors constitute one turn.

$$\text{total no. of turns in these angles} = \frac{2\theta_m}{360} \times zI$$

$$\text{Demagnetising Amp-turns per pair of poles} = \frac{2\theta_m}{360} \times zI$$

$$\text{Per pole} = \frac{\theta_m}{360} \times zI$$

$$AT_d/\text{pole} = \frac{\theta_m}{360} \times zI$$

$$\begin{aligned} \text{cross magnetising Amp-} &\text{turns/pole} = \frac{z}{P} - z \times \frac{2\theta_m}{360} \\ &= \frac{z}{P} \left[\frac{1}{P} - \frac{2\theta_m}{360} \right] \end{aligned}$$

$$AT_c/\text{pole} = zI \left[\frac{1}{2P} - \frac{\theta_m}{360} \right]$$


(6)

Methods to limit cross-magnetising effect


① by using high reluctance pole tips

This is achieved by the following methods

- by using eccentric poles or chamfered poles
- by arranging pole shoe laminations left & right alternately.



eccentric poles




$$V\phi_a = \frac{A T_a}{R t}$$

② Armature flux path reluctance can be increased by drilling holes in the pole shoe?

→ due to above 2 methods main field flux is also decreased in addition to the armature flux. The deduction in main field flux can be compensated by adding extra turns to the main field winding therefore more copper is required, field copper loss ↑, efficiency ↓, cost of the m/c ↑.



③ By using compensating winding / compoles




(7)

- compensating winding is inserted in the slots made on the pole faces (pole shoe)
- compensating wdg is connected in series with the armature winding.
- mmf produced by the compensating wdg is acting opposite to the armature mmf. Therefore armature mmf under the pole is neutralised.

by using interpoles

- ~~interpoles axis~~ Interpoles are placed along the quadrature axis i.e. interpoles axis -
- interpole wdg is connected in series with the armature wdg through the brushes. so the cross magnetising effect at interpole region is neutralised.
- No. of interpoles required is equal to main poles 'p' but in order to reduce the cost of small DC machine no of interpoles used is equal to $\frac{p}{2}$.



Commutation

The process of current reversal in an armature coil by means of brushes & commutator segments is called commutation.



commutation period

It is the time required for commutator to advance one commutator segment.

$$T_c = \frac{w_c}{v_c} \text{ sec} = \frac{w_b}{v_c}$$

velocity = $\frac{\pi D n}{60}$ m/s

v_c = peripheral



$$w_b = w_c + w_m$$

$$w_c = w_b - w_m$$


$$w_c \approx w_b$$

t = time for current reversal


\rightarrow if $t = T_c$ (commutation period) \rightarrow ideal commutation

if $t > T_c \rightarrow$ delayed commutation / under commutation

if $t < T_c \rightarrow$ fast commutation / over commutation



①



⑨

100% brush segment ②

$$\text{coil } B \quad i = +I_C$$



$$\text{coil } B \quad i = 0$$

50% brush \rightarrow segment

①

50% brush \rightarrow segment

②



$$\text{coil } B, I = -I_C$$

100% brush \rightarrow segment ①

$$\text{coil } B \quad i = -I_C$$

Practical DC m/c has delayed commutation.
The reason for delayed commutation is

- i) cross-magnetising effect of AR
- ii) self inductance of a coil

$$\text{Reactance voltage } (V_x) = L_C \frac{2I_C}{T_C} \text{ volt}$$

$$\downarrow L \quad \frac{I_C - (-I_C)}{T_C} = 2 \frac{L I_C}{T_C}$$

Methods for improving commutation

- i) Resistance commutation
- ii) Voltage commutation

Resistance commutation

→ This is achieved by using carbon brushes instead of copper brushes.

→ with carbon brushes, the time constant of the local circuit is decreased & the response from coil decays at faster rate.

Voltage commutation

→ This is achieved by using interpoles. This method is suitable for both large & small DC m/c.

→ The direction of interpole flux is acting opposite to the armature flux along the brush axis. Therefore cross-magnetising effect in b/w the poles is neutralized.

→ The coil undergoing commutation cuts the interpole axis & dynamically induced emf is produced in it.

→ This emf is acting in phase opposition to the reactance voltage present in the coil. Therefore reactance voltage effect is also neutralized.

→ Good commutation is possible with interpoles.

DC Generator characteristics

(1)

1) Open circuit characteristics (O.C.C) E_0 vs I_f $|N=const.$

- This curve shows the relationship b/w the generated emf at no-load (E_0) and the field current (I_f) at constant speed.
- it is also known as magnetisation characteristics.

2) Internal characteristics (E_g vs I_a) $N=const.$



- This curve shows the relationship b/w the generated emf on load (E_g) & the armature current (I_a).
- This Emf (E_g) is less than (E_0) due to demagnetising effect of armature reaction. Therefore, this curve will lie below the O.C.C.

3) External characteristics (V_t vs I_L) $N=const.$

- This curve shows the relationship b/w the terminal voltage (V_t) & load current (I_L).
- The terminal voltage (V_t) will be less than E_g due to a voltage drop in the armature circuit. Therefore this curve will lie below the internal characteristics.

Characteristics of Separately excited DC Generator

① O.C.C




$N=const.$

(2)

$$E_g = \frac{P\phi z N}{60A}$$

$$\frac{DI}{V}$$



$$E_g \propto \phi N \rightarrow \text{speed const.}$$

$$E_g \propto \phi \propto I_p$$

$$\phi \propto I_p = \frac{V_{DC}}{R_{sh} + R_h} \quad \text{if } I_p = 0, \phi = 0$$

before saturation

$$\phi \propto I_p \quad \therefore E_o \propto I_p$$

→ The curve is a straight line starting from zero so long as the poles are unsaturated.


After saturation

→ As the flux density increases, the poles become saturated.

→ So increase in I_p will not increase E_o accordingly.

$$\phi = \phi_{sat} = \text{constant.} \quad E_o = \text{constant}$$

2) External characteristics (V_t & I_L) & internal
 3) characteristics (E_g vs I_a)




when DPST = open, $I_a = 0$ (Double pole single throw)

$$\phi = \phi_{rated} \quad E = V + I_p R_a$$

$$N = N_{rated} \quad V_{N.L} = E = E_o$$

DPST close

(3)



when load \uparrow , voltage \downarrow

Reason for voltage drop

- i) $I_a R_a$ drop
- ii) drop due to Armature reaction



Applications

- i) used as voltage source
- ii) battery charger
- iii) main exciter of synchronous machine

Characteristics of self-excited Generator

Cond's to buildup the Voltage

D) Shunt generator



- if the generator runs at a constant speed, some amount of e.m.f. will be generated due to residual magnetism in the main poles.
- This small e.m.f. circulates a field current which in turn produces additional flux to reinforce

④

the original residual flux.

- This process continues and the generator builds up the normal generated voltage following the O.C.C.
- The field resistance (R_f) can be represented by straight line passing through the origin.
- Voltage build up of the generator is given by the point of intersection of O.C.C and the field resistance line. 'P' is the point of intersection of two curves. Hence the generator will build up a voltage OQ .

conds for voltage build up of a self excited Generator :



- 1) There must be some residual magnetism in generator poles. Due to retentivity property, all magnetic materials possess some amount of flux called "residual magnetism" which is (5-10%) of rated value.
- 2) The connections of the field winding should be such that the field current strengthens the residual magnetism.
- 3) The resistance of the field circuit should be less than critical resistance (R_c). R_c is the total field resistance above which the generator fails to build up voltage.
- 4) The speed of the generator should be higher than the critical speed. Critical speed is the speed below which the generator fails to build up it's voltage.

(5)

when the generators build up voltage under load-condⁿ, the load resistance must be more than critical load resistance (R_{LC}).

O.C.C. in shunt generator

$E_0 \text{ vs. } I_L \text{ } |_{N=\text{const.}}$



when $I_L = 0$, $\phi = \phi_\infty$, $E = E_\infty = 0A$

$\rightarrow 0A = \text{residual flux voltage}$ (2-6) Volt

(*) Before saturation

$$\phi \propto I_L$$

$$E_0 \propto I_L$$


(*) After saturation

$$\phi = \phi_{\text{sat}} \text{ (after saturation)}$$

$$= \text{const.}$$

$$E_0 = \text{constant}$$

External & internal characteristics of shunt



Generators

(6)


when DPST open $I_a \approx 0$

$$V = E_g - I_a R_a$$

$$V_{N.L} = E_g = E_o$$

DPST close

Vary R_L in steps & record V_t & I_L



when load ↑, Voltage ↓

Reasons for voltage drop

- i) $I_a R_a$ drop
- ii) drop due to armature reaction
- iii) drop due to reduction in field current.

$$(\downarrow I_{sh} = \frac{V}{R_{sh}}) \quad \text{load } \uparrow, V_t \downarrow, I_{sh} \downarrow, \emptyset \downarrow$$


Applications

- i) used as ~~voltage~~ source for battery charging.
- ii) pilot exciters of alternators.

series Generator

(7)

voltage build up condⁿ



$$I_F = I_L$$

General voltage must have residual FLUX.



i) Field terminals are properly connected to the armature.

ii) The total series circuit resistance should be less than critical resistance (R_c).

iii) The speed of prime mover should be greater than critical speed.

iv) The speed of prime mover should be greater than critical speed.

O.C.C




DPST open

$$I_a = 0, V_{N.L} = E_g = f_o = 6-6 \text{ volt}$$

DPST close

Vary R_L in ~~series~~ steps & record

I_L



Uses :

boosters in DC transmission line to compensate line drops.

Note : The series generator is a variable voltage generator. It is therefore never used as a voltage source.

Compound generator


→ compound generator b Voltage build up process is same as shunt generator.

1. cumulative compound

- over compound ($V > E$)
- under compound ($V < E$)
- flat / level compound ($V = E$)

2) Differential compound

O.C.C



When DPST open


$$I_a \approx 0, I_L = 0$$

$$V_{N.L} = E_g = E_o$$

DPST close

Vary R_L in steps & record V & I .

(9)



\rightarrow when load \uparrow , $I_L \uparrow$, $I_a \uparrow$, $\phi_{se} \uparrow$

$$\phi_{sh} \propto I_{sh} = \frac{V}{R_{sh}} = \text{const.}$$

differential

$$\downarrow \phi_T = \phi_{sh} - \phi_{se} \uparrow, \downarrow E_g \propto \phi_T \downarrow, V \downarrow$$

cumulative

$$\text{load } \uparrow, \uparrow \phi_T = \phi_{sh} + \phi_{se} \uparrow, \uparrow E_g, \uparrow V$$

level/degree of compounding is controlled by connecting low resistance i.e. diverted across the series field winding.

~~$\phi_{se} \propto I_{sh} \text{ & } \phi_T$~~

Applications

Cumulative compound generator

- i) voltage source
- ii) battery charging
- iii) Excitor of alternator

Differential compound generator

- i) welding purpose

Voltage Regulation

$$\% VR = \frac{V_{NL} - V_{FL}}{V_{FL}} \times 100$$

The change in terminal voltage b/w Full load & No load

- The change in terminal voltage b/w Full load & No load w.r.t. Full load is known as voltage regulation.

+VR → differential, shunt, separately excited,

- VR → over, series

Zero VR → flat compound generator

Flat → load > F.L load < F.L
VR is +ve VR → -ve

→ poorest VR → series generator

→ +ve. poorest VR → differential generator

→ -ve. poorest VR → shunt generator

→ -ve. poorest VR → compound generator

→ +ve. poorest VR → differential generator

→ +ve. poorest VR → shunt generator

→ +ve. poorest VR → compound generator

→ -ve. poorest VR → series generator


→ -ve. poorest VR → flat compound generator

→ +ve. poorest VR → differential generator

Q) DC motor characteristics

- (i) N vs I_a }
- (ii) T vs I_a } elect. characteristics
- (iii) N vs T } mech. "

Shunt motor



$$\phi_a \propto I_{sh} = \frac{V}{R_{sh}} = \text{const.}$$

$$\text{i) } N \propto \frac{E_b}{\phi} \propto \frac{V - I_a R_a}{\phi}$$

$$\text{ii) } T \propto \phi I_a$$

$$T \propto I_a$$


$$\textcircled{1} \quad N \text{ vs } I_a$$

$$\frac{N \cdot L}{I_a} \quad I_a \approx 0$$

$$N \propto V$$

Mech load \uparrow ,

$$I_a \uparrow \quad N \propto V - I_a R_a$$




$$\text{due to AR, } \phi \downarrow \uparrow N \propto \frac{1}{\phi}$$

Dc shunt motor is a constant speed motor.

$$\textcircled{2} \quad T \text{ vs } I_a$$

$$T \propto I_a \quad (\phi = \text{const.})$$



~~At 0~~ AR considered, $\downarrow T \propto \downarrow \phi \ I_a$ (in light load, I_a less linear)

(iii) N vs T

$$T \propto I_a \Rightarrow T = k_1 I_a \quad \text{or} \quad I_a = \frac{T}{k_1}$$

$$N \propto \frac{V - \frac{T}{k_1} R_a}{\phi}$$

No load $I_a \approx 0, T_{em} = 0, N \propto \frac{V}{\phi}$

loaded load $\uparrow, T_{em} \uparrow, N \downarrow$


with AR $\phi \downarrow, N \uparrow$

Application

Fan
centrifugal pumps

lathe
machine tools

line shafting



Series motor

(*) $\phi \propto I_a$ (before saturation)

$$N \propto \frac{E_b}{\phi} \propto \frac{V - I_a(R_a + R_{sc})}{I_a}$$

$$\boxed{N \propto \frac{1}{I_a}}$$

$$T \propto \phi I_a$$

$$\boxed{T \propto I_a^2} \quad \checkmark$$

(*) After saturation

$$\phi = \phi_{sat} = \text{constant}$$

$$N \propto V - I_a(R_a + R_{sc})$$

$$\boxed{T \propto I_a}$$


① N vs I_a

$$\underline{\text{NL}} \quad I_a \approx 0 \left(\text{IN} \propto \frac{1}{I_a \rightarrow 0} \right)$$


→ NL speed of DC series motor is dangerously high speed.

→ Never start DC series motor without load.

load
mech load ↑, I_a ↑, N ↓



Q) gatc DC series motor field poles are saturated,



$b \rightarrow \text{ANI}$.


- ② T vs I_a $T \propto I_a^2$ before saturation
 $T \propto I_a$ after saturation



- ③ N vs T, $I_a \propto \sqrt{T}$
 $N \propto \frac{1}{I_a}$, $N \propto \frac{1}{\sqrt{T}}$

NL $T_{em} = 0$, $N = \infty$

mean load \uparrow , $\circ T_{em} \uparrow$, $N \downarrow$



$$P = T \omega$$

s.p. const.

$$T \omega = \text{const.}$$

$$\boxed{N \propto \frac{1}{T}}$$

\rightarrow DC series motor behaves as a constant power drive.

$T_{st} \propto I_{st}^2 \rightarrow$ series

$T_{st} \propto I_{st} \rightarrow$ shunt

→ series motor & T_{st} is very high.

(high inertia load)


Application

- i) Electric traction
- ii) lift
- iii) crane

Traction

Ⓐ $N = \text{low}, T \rightarrow \text{high}$

Ⓑ $N = \text{high}, T \rightarrow \text{less}$



Q) In which of the following motors loads are permanently connected to the shaft. Even H

- a) shunt c) cumulative compound
 b) Series d) differential

Q) In which of the following motors loads are directly connected to the shaft?

- a) Series b) Loco ————— Shaft

3) Compound Motor characteristics

$$N \propto \frac{E_b}{\phi_T}$$

$$N \propto \frac{E_b}{\phi_{Sh} + \phi_{Se}}$$

$$\phi_{sh} \propto I_{sh} = \frac{V}{R_{sh}} = \text{const.} \quad \phi_{se} \propto I_a$$

$$T \propto \phi I_a$$

$$T \propto (\phi_{sh} \pm \phi_{se}) I_a$$

$$T_{\text{em}} \propto \phi_{sh} I_a \pm \phi_{se} I_a$$

1) N vs I_a

No load

$$I_a \approx 0, \phi_{se} = 0$$

$$N \propto \frac{E_b}{\phi_{sh}}$$

$$\propto \frac{V}{\phi_{sh} n}$$

$$E_b \propto V - I_a (R_a + R_{se})$$

$$N = N_0$$

Load


mech load \uparrow , $I_a \uparrow$, $\phi_{se} \uparrow$

cumulative

$$\downarrow N \propto \frac{E_b}{(\phi_{sh} + \phi_{se})} \uparrow$$

diff

$$\uparrow N \propto \frac{E_b}{(\phi_{sh} - \phi_{se})} \downarrow$$



2) T vs I_a

$$T \propto \left(\frac{\phi_{sh} I_a}{\text{shunt}} \pm \frac{\phi_{se} I_a}{\text{series}} \right)$$

No load

$$I_a = 0, T = 0$$

cumulative




$T = \text{const.}$

$$\int (\varphi_{sh} - \varphi_{se}) I_a \uparrow = \text{const.}$$

③ N VS T

$$\frac{\text{No load}}{\checkmark} \quad T = 0, I_a = 0, N = N_0$$



Application

Moderate T at limited NL speed


- (i) punching m/c
- (ii) drilling m/c
- (iii) steel mills
- (iv) cement mills
- (v) paper mill

cumulative compound

(no application for
differential compound
motor)

Q) if all the motors are designed to produce same torque at F.L. which of the following motor produces more torque before full load.

- a) Series
- b) Shunt
- c) Cumulative compound
- d) differential compound



before Full load

Torque in Descending order


differential > shunt > cumulative > series

After F.L.

series > cumulative > shunt > differential

→ if all the motors are designed to produce same speed at F.L. then which motor has higher torque?

Series > Cumulative > Shunt > Differential




(Q) DC shunt generator build up its rated voltage if its direction of rotation is reversed then generator will

a) build up voltage with same polarity

b) " " " opposite "


c) No voltage build up

d) None of the above




(Q) DC shunt generator build up its rated voltage if its direction of rotation & Field connections are reversed, then the m/c will (same option).

build up voltage with opposite polarity



$$\phi \uparrow, E_g \uparrow$$

Q) DC shunt generator build up its rated voltage if the directn of rotation & residual flux directn are reversed then generator will




$$E_g \propto \Phi_\delta N$$

$$\phi_f \downarrow, E_g \downarrow,$$

No voltage build up

Q) The shunt generator build up its rated voltage if its directn of rotation, residual flux directn & field terminals are reversed then generator will



$$\phi_f \uparrow, E_g \uparrow,$$

build up voltage with same polarity.

Note

during voltage build up residual flux voltage initiates the voltage build up process.

(10) Speed control of DC motors

Base speed or rated speed / nameplate speed :


→ It is the speed of the motor at rated supply voltage & rated flux.

constant power drive

The shaft power remains constant for a given speed range.

$$P_{sh} = T_{sh} \times \omega = \text{const.}$$


$$T \propto N = \text{const.}$$



ex : electric traction, lifts, cranes.

→ DC series motor behaves as a constant power drive.

• Adjustable speed drive



advantages of adjustable speed drives

Speed driver

i) smooth & noiseless operation

ii) power saving

ex: steel mills, cement mills, paper mills, coal mines etc

Speed control methods

Speed control \rightarrow load on the m/c = constant


$$N \propto \frac{E_b}{\phi} \propto \frac{V - I_a R_a}{\phi}$$

i) Flux control method
Field weakening method

ii) Armature resistance control method

or


iii) Armature voltage control method



T_e

① FLUX control method

shunt motor




$$\phi_1 \propto I_{sh} = \frac{V}{R_{sh}} = \text{Rated } I_f$$

$$I_{ar} = \frac{V - E_b}{R_a} = \text{Rated armature current}$$

$$N_1 = N_{\text{rated}}$$

$$N_1 \propto \frac{E_b}{\phi} \propto \frac{V - I_{ar} R_a}{\phi_1}$$

Field regulator



$$\phi_2 \propto I_{sh} = \frac{V}{R_s + R_{sh}}$$

$$\phi_2 < \phi_1$$

$$N_2 \propto \frac{E_b}{\phi_2} \propto \frac{V - I_{ar} R_a}{\phi_1}$$

$$N_2 > N_1 = N_{\text{rated}}$$

→ Above Negated possible.

$$\phi \downarrow, N \uparrow, F_b \propto \cancel{N} \uparrow \underset{\text{const}}{\cancel{=}} \text{const.}, F_{b2} = F_{b1}$$

$$T_{a2} = \frac{V - F_b}{K_a}$$

$$\frac{V - E_b}{k_B} = T_a$$


~~Estimated Total~~

$$P_{\text{mech}} = E_b I_a$$

$$= \text{const.}$$

$\downarrow T \propto \downarrow \phi$ I_a , $N \uparrow$ $\rightarrow P d^T N^l$ ~~and score~~

\Rightarrow const. power variable torque to drive.
 (ac-synchro motor)



Series motor

Flux of series motor can be controlled by
using the following methods


i) diverters control

ii) Tapped Field control

iii) Series & parallel connection of field coils

1) diverters control

without diverters




$$I_{a1} = F_a(\text{rated})$$

$$\phi \propto I_{a1}$$

$$N_1 \propto \frac{E_{b1}}{\phi}$$

$$N_1 \propto \frac{V - I_{a1}(R_{a1} + R_{sc})}{I_{a1}} \quad \dots (i)$$

with diverters



$$\phi_2 \propto I_{se} = I_{a2} \times \frac{R_d}{R_d + R_{se}}$$

$$\phi_2 < \phi_1$$


$$N_2 > N_1$$

$$N_2 \propto \frac{E_{b2}}{\phi_2} \propto \frac{V - I_{a2}(R_{a2} + \frac{R_d R_{se}}{R_d + R_{se}})}{I_{se}} \quad \dots (ii)$$

$$\frac{N_1}{N_2}$$

(rate of rise) (falling off)

③ Tapped Field control (Fractional motors)



$$\phi \propto m.m.f.$$

$$\phi \propto T I_a$$

At ① $\phi_1 \propto T_1$

$$T_1 > T_2 > T_3$$

At ② $\phi_2 \propto T_2$

$$\phi_1 > \phi_2 > \phi_3$$

At ③ $\phi_3 \propto T_3$


$$N_1 < N_2 < N_3$$

drawback


step by step speed control method

③ Series, parallel connection

(I)



series




$$\phi_1 \propto m.m.f.$$

$$= I_a, \frac{T_{se}}{2} + I_a, \frac{T_{se}}{2}$$

$$\phi_1 \propto I_a, T_{se}$$

parallel



$$\phi_2 \propto m.m.f.$$

$$= \frac{T_{se}}{2} \times \frac{I_{a2}}{2} + \frac{T_{se}}{2} \times \frac{I_{a2}}{2}$$

$$\phi_2 \propto \frac{T_{se} I_{a2}}{2}$$

① const. 'P' drive

$$P_2 = P_1 \Rightarrow \cancel{\phi_2} I_{a2} = \cancel{\phi_1} I_{a1}$$

$$I_{a2} = I_{a1}$$

$$\phi_1 \propto I_{a1} T_{se}$$

$$\phi_2 \propto I_{a2} \frac{T_{se}}{2}$$

$$\frac{N_2}{N_1} = \frac{\phi_1}{\phi_2} = \frac{I_{a1} T_{se}}{I_{a2} \frac{T_{se}}{2}} \times 2$$

$N_2 = 2 N_1$

② const. torque drive

$$T_2 = T_1 \Rightarrow \phi_2 I_{a2} = \phi_1 I_{a1}$$

$$\rightarrow \phi_2 \frac{T_{se} \frac{I_{a2}}{2}}{I_{a2}} = T_{se} I_{a1} I_{a1}$$

$$\rightarrow \frac{I_{a2}^2}{2} = I_{a1}^2$$

$$\rightarrow I_{a2}^2 = 2 I_{a1}^2$$


$$\rightarrow I_{a2} = \sqrt{2} I_{a1}$$

$$\frac{N_2}{N_1} = \frac{\phi_1}{\phi_2} = \frac{I_{a1} T_{se}}{\frac{I_{a2}}{2} T_{se}} = \frac{2 I_{a1}}{I_{a2}} = 2 \times \frac{I_{a1}}{I_{a2}}$$

$N_2 = \sqrt{2} N_1$

③ armature resistance control method

shunt motor




$$\phi d I_{sh} = \frac{V}{k_{sh}}$$

$$I_{a1} = \frac{V - E_b}{R_a}$$

= rated armature current

$$N_1 \propto \frac{E_b 1}{\phi_1} \quad N_1 \propto \frac{V - I_a 1 R_a}{\phi_1}$$

$$N_1 = N_{\text{rated}}$$



$$\phi_2 \propto I_{sh} = \frac{V}{R_{sh}}$$

$$\phi_2 = \phi_1 \quad \checkmark$$

$$I_{a2} = \frac{V - E_{b2}}{R_a + R_e}$$

$$N_2 \propto \frac{E_{b2}}{\phi_2} \quad \therefore N_2 \propto \frac{V - \Phi I_{a2} (R_a + R_e)}{\phi_2}$$

$$\frac{N_2}{N_1} = \frac{V - I_{a2} (R_a + R_e)}{V - I_{a1} R_a}$$

$$\text{if } R_e \uparrow, N \downarrow, \boxed{E_{b2} \propto \Phi N} \quad \therefore \boxed{E_{b2} < E_{b1}} \quad \checkmark$$

$$I_{a2} = \frac{(V - E_{b2} \downarrow) \uparrow}{\uparrow (R_a + R_e \uparrow)} = \text{const.}$$

= rated armature current.

$$T \propto \Phi I_a \rightarrow \text{const.}$$

$$N \downarrow, \boxed{P \propto T N \downarrow}$$

\therefore It ^{behaves} as constant torque & variable $P_{\text{distr.}}$

$$R_e \gg R_a \rightarrow \text{neglected}$$

$$\frac{N_2}{N_1} = \frac{V - I_a R_e}{V}$$

$$\eta \approx \frac{P_{\text{mech}}}{P_{\text{in}}} = \frac{E_b I_a}{V I_d} \quad I_L \approx I_a$$

$$\eta \approx \frac{E_{b2}}{V} = \frac{V - I_a (R_a + R_e)}{V}$$

$$R_a \ll R_e$$

$$\therefore \eta = \frac{V - I_a R_e}{V} = \frac{N_2}{N_1} \times 100$$

$$N_1 = 1000 \text{ rpm}$$


$$\eta_{\text{at}} \quad N_2 = 1000 \text{ rpm}, \quad \eta = 100\%.$$

$$= 800 \text{ rpm}, \quad \eta = 80\%$$

$$= 600 \text{ rpm}, \quad \eta = 60\%$$

$$= 100 \text{ rpm}, \quad \eta = 10\%$$

$N_2 < N_1$
only below rated speed




series motor

$$\frac{N_2}{N_1} = \frac{E_{b2}}{E_{b1}} = \frac{V - I_{a2} (R_a + R_{se} + R_e)}{V - I_{a1} (R_a + R_{se})}$$

$$(R_a + R_{se}) \ll R_e$$

$$\frac{N_2}{N_1} = \frac{V - I_a R_e}{V}$$




Armature voltage control method (below rated speed)

i) (By using static rectifiers)

(+) run the motor as separately excited

motor



$$\phi = \phi_{\text{rated}}$$

= const.

$$N \propto V_a$$


$$V_a = V_{\text{rated}}$$

$$N = N_{\text{rated}}$$

$$\alpha \uparrow, V_a \downarrow, \quad \downarrow N \propto V_a \downarrow$$

ii) Series - parallel connection of series motor

Traction



$$N_1 \propto \frac{E_b}{\phi}$$

in series

$$\frac{\phi}{\phi} \propto I_a$$


Neglect $I_a(R_a + R_{sc})$ drop

$$N_1 \propto \frac{V}{I_a}$$

$$N_1 \propto \frac{V}{2I_a}$$

$$T_1 \propto I_a^2 \quad \dots \text{ii}$$

Parallel



$$\phi_2 \propto \frac{I_a}{2}$$

$$N_2 \propto \frac{V}{(I_a/2)}$$

$$N_2 \propto \frac{2V}{I_a} \quad \dots \text{iii}$$

$$T_2 \propto \left(\frac{I_a}{2}\right)^2 \quad \dots \text{iv}$$

$$\frac{③}{①} = \frac{N_2}{N_1} = \frac{2V}{I_a} \times \frac{2I_a}{V} = 4$$

$$N_2 = 4N_1$$

$$N_{\text{parallel}} = 4 N_{\text{series}}$$

$$\frac{\text{ii}}{\text{iv}} = \frac{T_1}{T_2} = \left(\frac{I_a^2}{I_a^2} \right)^q$$


$$T_1 = q T_2$$

$$\Rightarrow T_{\text{se}} = q T_{\text{parallel}}$$

Traction

Ward - Leonard Systems

→ run motor as separately excited motor.



→ combn of flux control & armature voltage control.

$$E_b \propto \Phi \propto I_{Fm}$$

$$\Phi_g \propto I_{Fg}$$

$$E_g \propto V \propto I_{Fg}$$

→ armature voltage control obtained by adjusting the I_{Fg}

Case - 1

$$V = V_{\text{rated}}$$

$$I_a = \frac{V - E_b}{R_a} = \text{const.}$$

$$I_{Fm} = \text{rated } I_f$$

$$= \text{rated } I_a$$

$$N = N_{\text{rated}}$$

(*) armature voltage control

$$N \propto V. (\text{below } N_{\text{rated}} \text{ speed})$$

→ obtained by adj'g I_{Fg}

$$I_{Fg} \downarrow, V \downarrow, N \downarrow \quad I_a = \frac{V - E_b}{R_a(X)} = \text{const.}$$

$$\text{if } V \downarrow, N \downarrow, E_b \downarrow$$

$$T \propto I_a \rightarrow \text{constant}$$

$$P = T \times \omega \quad P \propto N$$

motor behaves as a constant torque & variable

speed drive

(*) flux control method (Above N_{rated})

→ obtained by adjusting I_{Fm}

but ~~to~~ maintain $V = V_{\text{rated}}$

$$\downarrow \phi \propto I_{Fm} \downarrow, N \uparrow, E_b = \text{const.}$$

$$E_b \propto \phi \propto N \uparrow$$

$$I_a = \frac{V - E_b}{R_a} = \text{constant. armature current}$$

$$\downarrow T \propto \phi \downarrow I_a$$

$$P \propto T \downarrow N \uparrow = \text{const.}$$

→ motor behaves as constant power variable


torque drive, (const. T & variable)

below N_{rated}

P

P

above N_{rated} (const. p
& variable torque)



Advantages

1) The speed of the motor can be controlled in wide range.

2) Smooth speed control is possible.

3) both above & below rated speed possible,
 $N_2 = 4N_1$ (with interpole)

$N_2 = 2N_1$ (without interpole)

4) wide range of speed control is possible in either direction. Good efficiency.

disadvantages

1) MG set is required,

high initial cost.

5) efficiency at low speed is better as compared to other methods. (armature resistance control method).